






x1



x1



x6



x3



x3




x6




x6



x1







1








$$H_1 > H_2 \Rightarrow H_2 \rightarrow H$$

$$H_1 < H_2 \Rightarrow H_1 \rightarrow H$$





2



<i>L[mm]</i>	1200	1500	1800	2000	2400	3000
<i>n[szt]</i>	3	3	4	4	5	6

3



nx Ø4

x6

70

D-60

h+8

x6



5

nx Ø4x16






x3

nx Ø4x16



$D[mm]$	<500	≥ 500
$n[szt]$	2	3



6



7



$\text{Ø}4 \times 16$

