





H Trim






2


Typ	60	70	80	90	100
D_p [mm]	1448	1648	1848	2048	2248
n [szt]	5	6	7	7	8




3





4




5







6




x2




7




x2




8




8a




8b




9




1





2





3



x2







2'



Typ	110	130	150	170	190
D_p [mm]	2452	2852	3252	3652	4052
$\frac{D_p}{2}$ [mm]	2x 1226	2x 1426	2x 1626	2x 1826	2x 2026
n [szt]	8	10	10	12	14



3' → 3 x2

4' → 4 x2

5' → 5 x2

6' → 6 x2

7' → 7 x2

8' → 8 x2

9' → 9

